

OTSEGO COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Otsego (County)	Located In	Charlton Twp. North	Corner Code #
1. Public Land Survey	T	31N R 1W	K-4
	T	_____	_____
2. Property Controlling in Section	S	T _____ R _____	_____
	S	T _____ R _____	_____
3. Miscellaneous Property in Section	S	T _____ R _____	_____
	S	T _____ R _____	_____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on August 8, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11	●	12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-4 ¼ Corner common to Sections 11&12, T31N, R01W

- 1850 – GLO – Austin Burt- Set ¼ sec. post
- Beech 12 S48E 17
- Hem. 20 N18W 18

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-4 ¼ Corner common to Sections 11&12 T31N, R01W

Found no evidence remaining of the original corner or its accessories. Set standard DNR cap on 1" x 36" galvanized pipe by single proportionate measurement to GLO distance. Distance from K-3 to K-5 measures 13.92' short of original GLO measurement. Accepted as a faithful and careful re-establishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-4 ¼ Corner common to Sections 11&12 T31N, R01W

Standard DNR cap on 1" x 36" galvanized pipe

- Wit:
- N01°E 28.75' to set N&T on E side 8" Beech
 - S68°E 32.35' to set N&T on N side 10" Ash
 - S05°W 19.80' to set N&T on W side 8" Ash
 - S85°W 29.41' to set N&T on S side 3" Ironwood

Set Blue Post 1' North



Signed by: Carl T. Kiiskila
 Surveyor's Michigan License No.: 33981

Date: 10-14-13