

OTSEGO COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

| Otsego (County) | Located In | Charlton Twp. North | Corner Code # |
|---|------------|------------------------|---------------|
| 1. Public Land Survey | T | 31N R 1W | M-4 |
| | T | 31N R 1E | A-4 |
| 2. Property Controlling in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous Property in Section | S | T | R |
| | S | T | R |

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on June 19, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

M-4 East ¼ corner section 12, T31N, R01W

1840 – GLO – John Mullett - Set ¼ section post.
Fir 12" S19°W 27'
Birch 10" N4°E 37'

1993 – A-4 Montmorency Co. Liber -1, page 499
Carl R. Johnson P.S. #30083 – Set corner by single proportionate measurements between found section corners, no other evidence found.
Set ½" bar with cap.
10" Spruce S50°W 15.10'
6" Twin Birch N30°W 40.00'
4" W. Pine N70°W 33.40'
Centerline old E/W grade North 48.00'

1994- A-4 Montmorency Co. Remonumentation
Liber -1, page 499 Larry G. Beauregard
P.S. #18654 found ½" bar set by
Carl R. Johnson P.S. #30083 in 1993
set Montmorency Co. Monument
North 47' old R.R. grade
15" W. Balsam N60°W 98.33'
4" W. Pine N70°E 33.35'
20" W. Pine N05°E 95.78'
11" Spruce S50°W 16.01'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

M-4 East ¼ corner section 12, T31N, R01W

Found Montmorency Co. Monument
fitting Carl Johnson's survey in section 7 and
one of L. Beauregard's witnesses.
S46°W 16.18' to set N&T on SE side 20" Spruce
Corner is accepted as a careful and faithful
reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-4 East ¼ corner section 12, T31N, R01W
Montmorency Co. Monument

Wit: N36°E 13.19' to set N&T on N side 8" Spruce
S46°W 16.18' to set N&T on SE side 20" Spruce
N72°W 18.44' to set N&T on N side 6" Spruce
N01°E 95.75' to set N&T on W side 29" W. Pine

Set Blue Post 1' North

Signed by:

Carl T Kiiskila

Date:

10-14-13

Surveyor's Michigan License No.:

33981

