

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Otsego Located In \_\_\_\_\_ Corner Code # \_\_\_\_\_  
 (County)

1. Public Land Survey	T _____	R _____		
	T _____	R _____		
2. Property Controlling in Section	S _____	T _____	R _____	
	S _____	T _____	R _____	
3. Miscellaneous Property in Section	S <u>26</u>	T <u>31N</u>	R <u>01W</u>	<u>10</u>
	S _____	T _____	R _____	

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on October 27, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

10 - S 1/16 Cor. comm. to sec.'s 26 & 27, T31N, R1W

1991 - L.C.R.C. (DNR in house record) - Carl R. Johnson, P.S.#30083 - Set 5/8"x32" CIR#30083 by standard survey procedure for subdivision of a section.  
 W. Birch 14" S81°W 12.6'  
 Maple 5" N34°W 12.6'  
 Maple 8" N33°E 49.4'  
 Maple 5" S36°E 30.0'

1991 - MDNR Survey Map - Carl R. Johnson, P.S.#30083 - Shows setting corner by S.P. on map.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

10 - S 1/16 Cor. comm. to sec.'s 26 & 27, T31N, R1W

Found 5/8" CIR#30083 per Carl R. Johnson in 1991. Accepted found CIR as the best available evidence for the position of the corner. Replaced plastic cap and added stamped 2" dia. alum cap to iron. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

10 - S 1/16 Cor. comm. to sec.'s 26 & 27, T31N, R1W

Stamped 2" dia. alum. cap on 5/8"x 32" rebar

Wit: N25°E 49.89' to set N&T on SE side 12" R. Maple  
 \*S43°E 30.10' to set N&T on SW side 9" R. Maple  
 \*S75°W 12.71' to set N&T on N side 15" Dead W. Birch  
 \*N41°W 13.10' to set N&T on SW side 8,9,3" Triple R. Maple  
 S51°W 27.93' to set N&T on SE side B. Fir  
 Nailed Location tag to Cedar Fence Post 0.5' to SW

\* Witness of previous record.

Signed by: Carl T. Kiiskila  
 Surveyor's Michigan License No.: 33981

Date: 11-10-10

