

DEC 01 1993

COMMISSION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

93 NOV 11 AM 11:54

Phyllis Robinson
REGISTER OF DEEDS
OTTAWA COUNTY, MI

For corners in

Ottawa Located In: Corner Code ##
(County)

1. Public Land Survey	T <u>8N</u> R <u>13W</u>	<u>G-5 (NW, 15)</u>
	T <u> </u> R <u> </u>	<u>Wright Twp.</u>
	T <u> </u> R <u> </u>	
	T <u> </u> R <u> </u>	
2. Property Controlling	S <u> </u> T <u> </u> R <u> </u>	
in Section	S <u> </u> T <u> </u> R <u> </u>	
3. Miscellaneous	S <u> </u> T <u> </u> R <u> </u>	
Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Donald W. Schiele, in a field survey on November 3, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-5 corner common to Sections 9, 10, 15 and 16 Wright Twp.

L.C.R.C. recorded in Liber 1, Page 391,

L.C.R.C. recorded in Liber 1, Page 393, 5-11-72.

R.R. Spike from County Ties 5-11-72.

R.R. Spike from County Ties

P.P. SE. 76.46'

Nail in Face of P.P.

SE. 76.46'

Tel. Pole SW. 75.15'

Nail in Face of Tel. Pole

SW. 75.15'

20" Maple N70°W. 174.01'

Nail in Face of 20" Maple

N70°W. 174.01'

St. Sign SE. 49.22'

St. Sign

SE. 49.22'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-5 Found R.R. Spike in 3/4" pipe in Monument Box and accepted as a careful and faithful perpetuation of the position of the original corner.

Found PK nail in SW side of Power Pole

SE 76.77'

Found Tag # 16042 & nail in NW side of Power Pole

SE 76.45'

Centerline Street Sign

SE 56.04'

Face of 44" Maple

N65°W 173.7'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-5 Set 3/4" X 24" solid bar with Ottawa County Remon Cap in Monument Box in place of R.R. Spike in 3/4" pipe.

SW corner brick face to House # 2379

N44°E 155.28' (E)

Set Ottawa County Remon Tag & nail in SW side of Power Pole

S44°E 76.76'

Set Ottawa County Remon Tag & nail in SE side of Power Pole

S33°W 52.20'

Set Ottawa County Remon Tag & nail in SW side of 44" Maple

N65°W 174.78' (E)

On Centerline asphalt roads North, East and South

On Centerline gravel road West

Signed by

Donald W. Schiele

Date

Nov. 8, 1993

Surveyor's Michigan License No.

23517

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

