

SURVEY & REMONUMENTATION

NOV 10 1993

COMMISSION

OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1993 SEP 29 PM 3:14

Donald W. Schiele
REGISTER OF DEEDS
OTTAWA COUNTY, MI

For corners in

Ottawa
(County)

Located In:

Corner Code ##

- | | | |
|---------------------------------------|------------|-----------------|
| 1. Public Land Survey | T 8N R 13W | H-5 (N 1/4, 15) |
| | T R | Wright Twp. |
| | T R | |
| | T R | |
| 2. Property Controlling
in Section | S T R | |
| | S T R | |
| 3. Miscellaneous
Property in Sec. | S T R | |
| | S T R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Donald W. Schiele, in a field survey on Sept. 18, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-5 corner common to Sections 10 and 15 Wright Twp.

T.C.R.C. recorded in Liber 3, Page 62

C.I.M.

Tel. Cable Marker	NW.	50.0'
P. Pole	SSE.	43.52'
CL St. Sign	S.	25.75'
10" Pear	NNE.	68.80'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-5
Found Broken C.I.M. in Monument Box and accepted as a careful and faithful perpetuation of the position of the original corner.
Found nail in West side of Power Pole SSE 43.57'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-5
Cemented 2" dia. Aluminum Ottawa Co. Re-mon. Marker #21272 on 4" long 3/4" dia. Steel Bar in Monument Box over C.I.M.
Set nail and Ottawa Co. re-mon. tag in West side of Power Pole N11°E 229.01' (E)
Set nail and Ottawa Co. re-mon. tag in West side of Power Pole S10°E 43.55'
Set nail and Ottawa Co. re-mon. tag in North side of Power Pole S78°W 207.17' (E)
NE corner Garage Footing N56°W 308.11' (E)
On CL gravel road North, on CL asphalt road East and West and on occupation line± South.

Signed by

Donald W. Schiele

Date

SEPT. 20, 1993

Surveyor's Michigan License No.

23517

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1976
REVISED MAY 14, 1975
REVISED JAN. 1983

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

