

SURVEY &  
REMONUMENTATION

NOV 10 1993

COMMISSION

OTTAWA COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ottawa  
(County)

Located In:

Corner Code ##

- |                         |   |    |   |     |                 |
|-------------------------|---|----|---|-----|-----------------|
| 1. Public Land Survey   | T | 8N | R | 13W | I-6 (E 1/4, 15) |
|                         | T |    | R |     | Wright Twp.     |
|                         | T |    | R |     |                 |
|                         | T |    | R |     |                 |
| 2. Property Controlling | S |    | T | R   |                 |
| in Section              | S |    | T | R   |                 |
| 3. Miscellaneous        | S |    | T | R   |                 |
| Property in Sec.        | S |    | T | R   |                 |

RECORDED

1993 SEP 29 PM 3:14

*Phyllis Adams*  
REGISTER OF DEEDS  
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Donald W. Schiele, in a field survey on Sept. 17, 19 93,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-6 corner common to Sections 14 and 15 Wright Twp.

I.T.R.C. recorded in Liber 3, Page 60

C.I.M.

24" Oak SE. 46.95'

CL E. end 8ft. diameter Corrugated NE. 35.20'

Metal Culvert

CL W. end 8ft. diameter Corrugated NW. 32.30'

Metal Culvert

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-6

Found C.I.M. Inscribed "Ottawa County Section Corner" and accepted as a careful and faithful  
perpetuation of the position of the original corner.

CL East end 8' diameter Corrugated Metal Culvert NE 35.27'

CL 34" Oak SE 47.6'

CL West end 8' diameter Corrugated Metal Culvert NW 32.36'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-6

C.I.M. 1" below surface

CL East end 8' diameter Corrugated Metal Culvert N62°E 32.36'

Set nail and Ottawa Co. re-mon. tag in SW side 34" Oak S41°E 47.67'

Set nail and Ottawa Co. re-mon. tag in NW side 5" Maple S64°W 34.23'

CL West end 8' diameter Corrugated Metal Culvert N64°W 32.36'

CL East and West Drain North 15'

On CL North and South gravel road

Signed by

*Donald W. Schiele*

Date

SEPT. 20, 1993

Surveyor's Michigan License No.

23517

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983