

# SURVEY & REMONUMENTATION

APR 24 1995

COMMISSION

## OTTAWA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

94 DEC 15 AM 11:46

For corners in

Ottawa  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 8N R 13W

K-13 (SW, 36)

T R

Wright Twp.

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

*Edythe Kellman*  
REGISTER OF DEEDS  
OTTAWA COUNTY, MI.

Register of Deeds Stamp & File Number

I, Donald W. Schiele, in a field survey on December 2, 19 94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

K-13 SE corner of Section 35 & SW corner of Section 36, Wright Twp.

Original Government Corner Record:

L.C.R.C. recorded in Liber 2, Page 479, 5-14-74

Set corner post of Sec. 35 & 36

Fd. Solid iron

Post

MSHD tag in P. Pole

NE 91.23'

Beech 12 N81E 67

Solid rod (NW cor. Sec. 1)

E 124.74'

Do 30 N12W 6

PK in P. Pole

SW 44.37'

Noah Brookfield, Deputy Surveyor

Edge of pavement

NE'ly 0.75'

April 12, 1837

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-13 Found Cast Iron Monument (broken), 11" below surface, and accepted as a careful and faithful perpetuation of the position of the original corner.

Found 5/8" Steel Bar East 124.84' (E)

Found PK nail in NE side of Power Pole S43°30'E 147.56' (E)

Found PK nail in SE side of Power Pole S31°30'W 44.41'

P.A. 345 OTTAWA COUNTY

PEER APPROVED

12/12/94

*Robert D. Nedewell*



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13 Set 3/4" X 8" Steel Bar with Ottawa County Remon Cap in concrete base over broken Cast Iron Monument, 2 1/2" below surface in Monument Box.

5/8" Steel Bar

East 124.84' (E)

Set Ottawa County Remon Tag & nail in NE side of Power Pole

S43°30'E 147.38' (E)

Centerline concrete Right-of-Way Marker

S03°E 59.43'

Set Ottawa County Remon Tag & nail in NW side of Power Pole

S31°30'W 44.52'

Set Ottawa County Remon Tag & nail in North side of 14" Ash

S71°30'W 124.15' (E)

On centerline asphalt road to West, extended East

Signed by

*Donald W. Schiele*

Date

Dec. 12, 1994

Surveyor's Michigan License No.

23517

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983