

SURVEY & REMONUMENTATION

APR 25 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
~~HOUGHTON & CANTON~~ COMMISSION
(County)

Located In:

Corner Code #

1. Public Land Survey T 48N R 37-38W M-3 A-3
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Recorded April 12 1994
St 1110 Clock P M. In
Lib 3 Page 198
J. W. Applebaum
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Section corner, Sections 6, 7, 1, 12; T.48N., R.37-38W.

I, Richard L. Drahn, in a field survey on October 28, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austin Burt, U.S. Deputy Surveyor, on June 18, 1847.
Original bearing trees:

Sugar	15"	S.55°E.	45 links	(29.70 feet)
Sugar	10"	N.58°W.	25 links	(16.50 feet)
Sugar	10"	N.60°E.	30 links	(19.80 feet)
Sugar	12"	S.25°E.	37 links	(24.42 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position from the stump holes of four original bearing trees. Distance and line to monumented corners north, south and east are in accordance with the original field notes. 1958 Forest Service location posted on 5" Ironwood N.20°W., 15.6 feet from corner position.

PEER GROUP

Approved

J. W. Applebaum 4-07-94
Out to Rep



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a standard 2" diameter by 30" long split base aluminum monument with a 3 1/4" aluminum cap stamped to read: T.48N., R.37-38W.; S.1, S.6, S.7, S.12; 1993; R.L.S. 21564: from which I established the following new blazed and scribed bearing trees and/or reference objects:

10"	Sugar Maple	N.55°E.	11.12 feet
10"	Sugar Maple	S.20°E.	28.69 feet
6"	Ironwood	S.82°W.	19.90 feet

A 6' steel sign post bears: S.62°E. 1.32 feet

Signed by Richard L. Drahn Date February 16, 1994

Surveyor's Michigan License No. 21564

U.S.F.S. E-25
E-1