

SURVEY &  
REMONUMENTATION

APR 25 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

~~HOUGHTON~~ **COMMISSION**  
(County)

Located in:

Corner Code #1

1. Public Land Survey

T 48N R 38-37W

M-4 A-4

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Recorded APRIL 12 1994  
at 1.10 o'clock P. M. in  
Lib. 3 page 199  
*Janeth A. Roach*  
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

$\frac{1}{4}$  Corner, Sections 7, 12; T.48N., R.37-38W.

I, Richard L. Drahn, in a field survey on December 2, 1993,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austin Burt, U.S. Deputy Surveyor, on June 18, 1847.  
Original bearing trees:

Spruce	26"	S.32°E.	14 links	( 9.24 feet)
Hemlock	18"	N.42°W.	24 links	(15.84 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record bearing and distance from stump remains of both  
original bearing trees. The 6.15 chain distance south to the "left bank of stream"  
and the 0.50 chain distance north to "ascend hill" are in accordance with the original  
field notes. Found a 14" cedar with Forest Service location poster and blazes with  
92 years of growth over them at S.20°E., 12.9 feet.

PEER GROUP

Approved

*Paul W. Applekamp 4-07-94*  
*Dist. Co. Rep.*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a standard 2" diameter by 30" long split base aluminum  
monument with a 3 1/4" aluminum cap stamped to read: T.48N., R.37-38W.;  $\frac{1}{4}$ ; S.7, S.12;  
1993; R.L.S. 21564: from which I established the following new blazed and scribed  
bearing trees and/or reference objects:

8"	Yellow Birch	N.88°E.	2.78 feet
8"	Spruce	S.04°E.	3.89 feet
12"	Black Ash	S.60°W.	16.88 feet

A 6' steel sign post bears: S.81°W. 1.21 feet



Signed by Richard L. Drahn

Date February 16, 1994

Surveyor's Michigan License No. 21564

U.S.F.S. G-25

6-1