

DEC 16 1996

JUDITH D. ROEHM  
Ontonagon County  
LC 4/ 85 JEM Fee: 9.00  
Page 1 of 1

**COMMISSION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>ONTONAGON</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T48NR 40W	E-7
	T___ R___	_____
	T___ R___	_____
	T___ R___	_____
2. Property Controlling in Section	S___ T___ R___	_____
	S___ T___ R___	_____
3. Miscellaneous Property in Sec.	S___ T___ R___	_____
	S___ T___ R___	_____

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Section Corner common to Section 16, 17, 20, & 21, T48N R40W.

I, Earl W. Applekamp, in a field survey on June 13, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, May 24, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

Sugar 12"	S40°E	17 links
W. Pine 20"	S45°W	28 links

**PEER GROUP APPROVED**  
*Earl W. Applekamp*  
COUNTY REPRESENTATIVE  
07-08-96

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. A gravel County Road runs North and South from the corner position. At the corner position I found a 1"x3 foot bolt below the gravel. A fence runs West from a point 30 feet South of the corner position. A local resident, Roy Paajanen, age 72, testified his father installed this fence and it was set South of the Section Line to accommodate a road running West which was used 50 plus years ago but is now covered with trees.

Research on file with the Ontonagon County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x24" rebar with a 3 1/4" stamped cap 4" below top of gravel. I established a reference monument, a 2 1/2"x30" aluminum pipe with a 3 1/4" cap stamped to read: County Remonumentation, T48N R40W, S16, S17, S20, S21, 1996, P.S. 17610. I also established three other bearing objects.

REF. MON.	S52°-44'-53"W	42.32'	- P. Pole	N05°-54'-43"E	293.19'
8" Aspen	S83°-36'-42"W	167.74'	- P. Pole	S51°-37'-20"E	34.37'



Signed by *Earl W. Applekamp*  
Surveyor's Michigan License No. 17610

Date June 20, 1996