

SURVEY &  
REMONUMENTATION

MAY 05 1997

JUDITH D. ROEHM  
Ontonagon County  
LC 4/ 71 JEM Fee: 9.00  
06/10/96 15:39  
Page 1 of 1

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>ONTONAGON</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T48N R 40W	G-10
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

$\frac{1}{4}$  Corner common to Sections 27 & 28, T48N R40W.

I, Earl W. Applekamp, in a field survey on May 3, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, May 31, 1851. Corner is a 14" Sugar.

ORIGINAL BEARING TREES:

Lynn 14" N45°E 10 links

PEER GROUP APPROVED  
Earl W. Applekamp  
COUNTY Clerk  
06-06-96

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. The corner position falls in a North-South County Road. A fence runs West from the corner position separating a farm field and a woods.

Corner was re-established by single proportionate measurement between opposite Section Corners to the North & South.

Research on file with the Ontonagon County Remonumentation Representative



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 3/4"x18" aluminum rod with a 3 1/4" cap, 4" below the gravel surface of the road. Cap is stamped to read: County Remonumentation,  $\frac{1}{4}$ , T48N R40W, S27, S28, 1996, P.S. 17610. I established one monument, a 2 1/2" aluminum pipe with a 3 1/4" stamped cap. I also established 3 bearing trees.

REF. MON.	S87°-22'-55"E	27.75'	7" Aspen	N33°-53'-02"E	53.14'
5" Aspen	N19°-16'-22"W	68.40'	9" Aspen	S70°-02'-45"W	29.09'

Signed by Earl W. Applekamp  
Surveyor's Michigan License No. 17610

Date May 31, 1996