

SURVEY & REMONUMENTATION

DEC 16 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JUDITH D. ROEHM
Ontonagon County
LC 4/ 61 JEM Fee: 9.00
Page 1 of 1

For corners in

ONTONAGON Located In: Corner Code #
(County)

1. Public Land Survey T48N R40W K-8
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

$\frac{1}{4}$ Corner common to Section 23 & 24, T48N R40W.

I, Earl W. Applekamp, in a field survey on April 23, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by J. Wells Burt, U.S. Deputy Surveyor, May 27, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

White Birch 9" N35°W 10 links
Spruce 10" S70°E 4 $\frac{1}{2}$ links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner was re-established by using an existing fence line running East & West and the centerline of a blacktop road running North & South. This position is within a few feet of a location by single proportionate measurement between opposite Section Corners, North and South.

Research on file with the Ontonagon County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At The corner position I set a 5/8"X24" Re-Bar with a 3 $\frac{1}{4}$ " stamped cap 2" below top of blacktop. I established one reference monument, a 2 $\frac{1}{2}$ "X30" aluminum pipe with a 3 $\frac{1}{4}$ " cap stamped to read: County Remonumentation, $\frac{1}{4}$, S23, S24, T48N R40W, R.M., 1996, P.S. 17610. I established three other reference objects.

REF. MON. S88°-49'-00"W 33.70' 12" Spruce S76°-19'-25"E 39.92'
REA P. Pole N06°-37'-24"W 224.29' REA P. Pole S19°-01'-04"W 86.63'

**ONTONAGON COUNTY
PEER APPROVED**

Earl W Applekamp
Ont Co RE-Mon Rep
5-07-96



Signed by Earl W Applekamp
Surveyor's Michigan License No. 17610

Date May 01, 1996