

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON
(County)

Located In: Corner Code #

1. Public Land Survey T48N R41W A-7 ✓
T48N R42W M-7
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

REMONUMENTATION

OCT 3 1997

COMMISSION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Section Corner common to Sections 18 & 19, T48N R41W &
Sections 13 & 24, T48N R42W.

I, Earl W. Applekamp, in a field survey on August 18 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William A. Burt, U.S. Deputy Surveyor, August 12, 1847. Set Cedar Post.

ORIGINAL BEARING TREES:

8" Aspen S15°E 3.96 feet
6" White Birch N77°W 9.90 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Apparent corner location is on a gravel road running North & South. This road has been in existence since the 1920's. At the apparent corner position a well maintained fence runs East along a woods & field line. Field is being actively farmed. Corner was re-established at intersection of the fence line and centerline of the gravel road. Corner position is in conformance with the original survey calls.

Research on file with the Ontonagon County Remonumentation Program Representative.

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REPRESENTATIVE

9-17-97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x12" rebar with a 3" stamped cap 5" below top of gravel road surface. I established a reference monument, a 2 1/2"x30" aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R41W, R42W, R.M., S18, S19, S13, S24, 1997, P.S. 17610. I also established 3 other reference objects.

REF. MON. N75°-21'39"E 34.91' - 9" Aspen N33°-33'-53"E 67.79'
Power Pole S38°-54'-18"W 61.67' - 4" Maple N59°-51'-21"W 87.63'



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date September 5, 1997