

APR 29 1996

COMMISSION

JUDITH D. ROEHM

08/09/95

Ontonagon County

14:00

LC 3/ 296 JEM

Feet: 9.00

Page 1 of 1

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in **ONTONAGON**
(County)

Located In:

Corner Code #

- | | | | | | |
|---|---|-----------|---|-----------|------------|
| 1. Public Land Survey | T | <u>48</u> | R | <u>41</u> | <u>B-3</u> |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| 2. Property Controlling
in Section | S | _____ | T | _____ | _____ |
| | S | _____ | T | _____ | _____ |
| 3. Miscellaneous
Property in Section | S | _____ | T | _____ | _____ |
| | S | _____ | T | _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
 $\frac{1}{4}$ Corner common to Section 6 & 7. T48N R41W

I, Earl W. Applekamp, in a field survey on May 22, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wills Burt, U.S. Deputy Surveyor, May 1851.
Set post.

Hemlock	20"	N62°W	12 Links (7.92 feet)
Maple	8"	N64°E	25 Links (16.50 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner was found. A county road runs North and East from the apparent corner location. The corner was set by single proportionate measurement between the SW and SE corner of Section 6. The location is consistent with the existing roads and the original field notes. This corner was one of the corners re-monumented in a Block of 6 Sections in which all original corners were re-established.

Research on file with the County Remonumentation Program Representative.

PEER GROUP APPROVED

Earl W Applekamp 8-08-95
COUNTY REPRESENTATIVE

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 $\frac{1}{4}$ "x30" split base aluminum pipe with a 3/4" cap stamped to read: COUNTY REMONUMENTATION, $\frac{1}{4}$, S6, S7, T48N R41W, 1995, P.S. 17610. I established the following bearing trees and objects.

6" Spruce	N70°W	9.75 Feet	Fence Post	S60°E	71.39 Feet
6" Spruce	N28°E	97.77 Feet	Steel Sign Post	South	1.14 Feet



Signed by Carl W. Applekamp
 Surveyor's Michigan License No. 17610

Date June 14, 1995