

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON
(County)

Located In:

Corner Code #

1. Public Land Survey

T48N R41W

D-11

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

SURVEY & REMONUMENTATION

MAR 23 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

 $\frac{1}{4}$ Corner common to Sections 29 & 32, T48N R41W.

I, Earl W. Applekamp, in a field survey on Oct. 20, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, June 1851. Set Wood Post.

ORIGINAL BEARING TREES:

10" Maple South 18 Links (11.88 feet)
20" Hemlock S66°E 9 Links (5.94 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original or subsequent evidence was found. Corner was re-established by single proportionate measure and on line between opposite Section Corners, East and West.

Research on file with the Ontongaon County Remonumentation Program Representative.

PEER GROUP APPROVED

Earl W. Applekamp 11-09-99
COUNTY REMONUMENTATION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2½"x30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N, R41W, S29, S32, $\frac{1}{4}$, 1999, P.S. 17610. I established 3 bearing trees and a reference object.

Nail in 5" Aspen N47°E 62.42' - Nail in 6" Aspen S35°E 55.15'
Nail in 7" Aspen S84°E 76.45' - 6' Steel Sign Post West 0.50'



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date October 22, 1999