LAND CORNER RECORDATION CERTIFICATE

| For corners in | Filing Requi | irement of Act 74, M | ich. P.A. 197 | 70 | | | |
|--|---------------------------|--------------------------------|-----------------|------------------|--|---------------------|---|
| | | | 1 | | | • | |
| ONTONAGON Located | d in: Co | rner Code # | | CIII | RVEY & | | |
| , | - 40N- 41M | H-5 | | REMONU | | LION | |
| 1. Public Land Survey | T_48NR_41W TR | C-n | | | THE SECOND SECOND | , | |
| · | T R | | | APR | 0 7 1998 | | |
| 2. Property Controlling S | ŢŖ | | * | | | | |
| in Section S | TR TR | | | SEC | MOIT | | |
| 3. Miscellaneous S | | | | | | | |
| Property in Sec. S | TR TR | | | Register | of Deeds St | amp & File | Number Number |
| 4. Lot No, Recorded Plat | | | | | | | . |
| 5. Private Claims | | | | 1 | DEFG | | TTT |
| 1/4 Corner common to Secti | ons 10 & 15, | T48N R41W. | ` | 2 6 3 | 54 | 3 | 21- |
| I, Earl W. Applekamp , in a field | d survey on <u>Nov</u> . | 08 , 19 <u>97</u> do hereby si | tate that under | 4 | - e — — b — | | 1112 |
| requirements of P.A. 74, Michigan P.A. of 19 conformance with regulations and rules theref | 970, the corner points in | nentioned in lines 1 and 2 | above were in | 5 | | - | |
| United States Department of the Interior, Bure | eau of Land Managemer | nt or by a decree of a Court | of Law and /or | 6 -18- | -1716 | -1/5 | 1413- |
| that the corner points mentioned in lines 3, 4 Board of Land Surveyors or by a Decree | | | | 7 | | | 1-1- |
| recovered, found as expressed below: | | | | 8 -19- | -2021 | 22- | 23 24 |
| NOTE: Not more than 2 corners, all in the on this certificate. | he same town and ran | nge, may be recorded | | 9 | 29 28 | 37 | 26 25 |
| on this certificate. | | age and | | 11 | 1 1 | | |
| | | | | 12 31 | 32 33 | 34 | 35 <u>3</u> 6- |
| | | | | 13 | . l , l l . , | <u> </u> | |
| A. Description of original monument ar | nd accessories and/o | r subsequent restoration | n: | | | | |
| Original corner establish June 17, 1851. Set Wood | | Burt, U.S. Deput | y Surveyo | or, | | | |
| ORIGINAL BEARING TREES: | | | | E GROUP | 71 | _ | |
| 40" White Pine | S35°E | 7.92 feet | Za | ilw | apples | | 2 |
| | s30°W | 6.60 feet | CC | DRITH BLICK | - SEALARY | 11-11 | -97 |
| B. Description of corner evidence four | nd and/or method ap | plied in restoring or rees | stablishing cor | ner: | | | |
| No original evidence was | found. Area | was extensively | logged a | ind burned | lover | | |
| in about 1900. Entire and | rea was owned | by Kimberly Cla | ark in the | past and | l they | | |
| logged it off about 1960 Corner was re-established | | | | | | o OF Mic | TATE OF THE PARTY |
| opposite section corners | | | | | , ring A | | CANTA |
| Research on file with the | a Ontanagon C | ounty Pemonument | tation Pro | vram | \$ X | EARL W. APPLEKAN | 7. 19 |
| Representative. | e ontonagon o | ourcy Nationalies | Lacion IIV |)gram | _ ~ - | ROFESSIO | - ~ . |
| • | | | | | EZ. | SURVEYO | R V |
| C. Description of monument for corner | r and acceptate est | tablished to perpetuate l | oceting the no | eition of the co | omer - A | 17610 | · SUP IN |
| At the corner position I | | | | | -h | OFESSION | VAL |
| a 3" cap stamped to read 1997, P.S. 17610. I est | l: County Remo | onumentation, T | 48N R41W, | S10, S15, | 7 4, | | 180- |
| 9" Soft Maple N88°W | 6.14' - | 8" Maple S | | 13.07 | • | · · · · · | |
| 7" Triple Maple N74°E | 16.46' – | 6' Steel Sign 1 | Post, Nort | th 0.79' | | • | |
| | | | | | | | |
| 4 | _ | | | | | - | |
| 2011/ | 7 01- | | ** | | 1007 | | |
| / • | plekany | | Date NO | vember 8, | 1997 | | |
| Surveyor's Michigan License No. | <u> </u> | 17610 | | | | , s | |