

SURVEY &
REMONUMENTATION

APR 25 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

ONTONAGON
(County)

Located In:

Corner Code #

1. Public Land Survey T 48 R 41 I-11
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

Section Corner 26, 27, 34 & 35, T48N R41W

I, Earl W. Applekamp a field survey on December 10, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Will's Burt, U.S. Deputy Surveyor.
Set Wood Post. Original Bearing Trees:

10" Spruce	N49°E	15 Links	(9.90 Feet)
8" Spruce	S47°E	25 Links	(16.50 Feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Near the corner there was a fence in good repair, running South and West and a fence in poor repair running North and East. The positions of the fences did not agree with the original survey distances. I talked to Al Hokens, a son of the person that installed these fences 50 years ago and he told me they were set 33 feet off to make provisions for a future road. The corner was set using this information and measurements taken on four sides of Section 26 and 27.

Additional research information on file with the County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2½" aluminum pipe with a 3¼" cap stamped to read: County Remonumentation, S.26, S.27, S.34, S.35, T48N R41W, 1994, P.S. 17610. The following bearing trees and reference objects were used to tie in the corner.

16" White Pine	S54°E	170.32 Feet	Steel Sign Post South 1.48 Feet
7" Poplar	N45°E	43.26 Feet	
4" Poplar	S36°W	70.20 Feet	

Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date December 13, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

Recorded December 19 1994
at 2:30 o'clock P. M. in
Liber Survey 3 page 250
James M. [Signature]
Register of Deeds

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

ONTONAGON COUNTY

PEER APPROVED

Earl W. Applekamp
Ant Co Rep
12-15-94



250