

APR 25 1995

COMMISSION

**LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in
Ontonagon
(County)

Located In:

Corner Code **##**

1. Public Land Survey T 48N R 42W
- T R
- T R
- T R
2. Property Controlling S T R
- in Section S T R
3. Miscellaneous S T R
- Property in Sec. S T R

C-D-7

Other

#5 pm

Recorded August 31 1994
at 2:05 o'clock P.M. In
Liber 3 page 210
Julie Marley Deputy
Register of Deeds

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Meander corner

I, John R. Garske, in a field survey on May 17, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original survey by Austin Burt, U.S.D.S., on August 2-12, 1848. Set a cedar post. Original Bearing Trees: 12" cedar - S40°E - 11 links; 10" cedar - N34°E - 12 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a 1" iron pipe approximately 5 feet out from the shore in Lake Gogebic at corner position. I accepted this corner position as correct due to its use in several surveys of record, its harmonious location with local residents and general use and acceptance. I set a new corner position on the section line at the top of the bank overlooking Lake Gogebic and left the iron pipe in the lake. I monumented the corner and updated accessories as noted below to state and county specifications.

Research on file with County Remonumentation Program Representative.

**ONTONAGON COUNTY
PEER APPROVED**

Earl Applekamp Co. Rep.
8-17-94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I set a 3/4" x 30" rebar with a 3 1/4" aluminum cap on the shore of Lake Gogebic. Cap is stamped: County Monumentation, M.C., S-17, S-20, T48N, R42W, 1994, RLS 28410. I established the following bearing trees and reference objects:

Steel sign post - N22°W - 1.80 feet
5" ash - N42°W - 10.82 feet
5" basswood - Due West - 6.38 feet

Edge of lake-Due-West 18 feet more or less
4" maple - S48°E - 6.96 feet
Found 1" iron pipe-Due West-21.19 feet

Signed by *John R. Garske*

Date 6/8/94

Surveyor's Michigan License No. 28410

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

