DEC 1 6 1996

JUDITH D. ROEHN Ontonason County

LÇ

3/363 HEL

10/26/95

14:05

Fee: 9.00 fage 1 of

NOISSIMMOD

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	r corners in	- ,	•						
	ONTONAGON	Located In:	Corner Code #						
_	(County)	т <u>48N</u> R <u>42W</u>	B-C-3 012	\					
1.	Public Land Survey	T R T R	4				•		
2.		ST R ST R							
3.	Miscellaneous	S T R							
	Property in Section	\$ T R		Register of	Deed	ds Stam	p & File	Numb ———	er
4.	Lot No, Reco	orded Plat		Á	в С	DEF	- G Н	1 3	KLM
5.	Private Claims								
	Meander Corner	common to Secti	ons 6 & 7, T48N R	42W. 3		-89	10-		12
ı, Ę	Carl W. Applekamp, in	a field survey on	October 16 , 19 95	, 5	┼		+	-	
			A. of 1970; the corner points menti		ia- -	-1716	5 15-	14-	13-
			rules therefore as required in the cu nent_of_the_Interior_Bureau_of		 -				
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and					19—	-202	1-22-	23-	24-
5 a	bove were in conformance with	n the rules of the Michigan B	oard of Professional Surveyors or	by a g	 				
	cree of a Court of Law; establist expressed below:	ned, re-established, monumer	nted, re-monumented, recovered, f	10	30-	-29 2t	3——27—		25—
NO	TE: Not more than 4 corner on this certificate.	s, all in the same town and	d range, may be recorded	11 12 13 13 13	31	-3233	334	35-	-36
A.	Description of original mo	nument and accessories a	and/or subsequent restoration	:					

Original corner established by Austin Burt, U.S. Deputy Surveyor, August 1848. Set Maple Post.

ORIGINAL BEARING TREES:

Maple 8" S42°W 36 links (23.76 feet) Maple 6" N37°W 19 links (12.54 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Original corner is 60-70 feet into the lake. Lake Gogebic was dammed and water was raised in the 1930's.

No subsequent evidence was found. Corner was re-established Easterly of the $\frac{1}{4}$ Corner on a projection of a line between the SW Corner of Section 6 and the $\frac{1}{4}$ Corner common to Sections 6 and 7. Research on file with County Remonumentation Program Representative.

> PEER GROUP APPROVED COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 3/4"x96" aluminum rod, with a $3\frac{1}{4}$ " cap stamped to read: T48N R42W, S.6, S.7, M.C., 1995, P.S. 17610. I established the following Steel Sign Posts to witness the Corner.

Steel Sign Post West 15.33 feet - Steel Sign Post East Steel Sign Post South 11.83 feet - Steel Sign Post North

7610.
orner.

10.62 feet

1.20 feet

The position of the corner:

OF MICHONA APPLEKAMP

PROFESSIONAL

SURVEYOR

NO.

1.7610

POFESSIONAL

OFESSIONAL

OFESSIONAL No. 17610

APOFESSIONAL

Signed by Earl W	linglekaup	
Surveyor's Michigan License No.	17610	

October 17, 1995 Date_

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 **REVISED MAY 14, 1975** REVISED JAN. 1983