

JUDITH D. ROEHM

1F

Ontonagon County

Page 1 of 1

LC

5/189

JEM Rec. Date 05/17/99 Time 12:51

RECORDING FEE:

9.00

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON

(County)

Located in:

Corner Code #

1. Public Land Survey

T 50NR 42W

F-3

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____ $\frac{1}{4}$ Corner common to Section 4 & 9, T50N R42W.

I, Earl W. Applekamp, in a field survey on April 14, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Austin Burt, U.S. Deputy Surveyor,
June 15, 1848. Set Sugar Post.

ORIGINAL BEARING TREES:

12" Lymn	S10°W	17.16 feet
18" Hemlock	N10°E	3.96 feet

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REMONUMENTATION

5-11-99

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner position is on an abandoned RR grade which is now graveled in this area and being used as a road. No other evidence was found. Corner was re-established by single proportionate measure between opposite corners East and West.

Research on file with the Ontonagon County Remonumentation Program Representative

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x24" rebar with a 3" aluminum cap 8" below the gravel surface of the road and 7 feet South of the center-line. The cap is stamped to read: County Remonumentation, T50N R42W, S4, S9, $\frac{1}{4}$, 1999, P.S. 17610. I established three bearing trees and a reference object.

Nail in 13" Hemlock	N16°E	80.83'	- Nail in 11" Hemlock	S23°E	47.39'
Nail in 11" Hemlock	N68°E	101.10'	- 6' Steel Sign Post,	Due South	2.92'

Copper Range Coordinates N30005.79' - E32623.36'

Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date April 20, 1999