

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 25 T 51N R 37W S _____ T _____ R _____ S 36 T 51N R 37W	16 (GCDB 660200) 5 (GCDB 640160)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 06/10/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 25) East 1/16 corner between Sections 25 and 36. Not previously monumented.

(5-Sec. 36) Center-North 1/16 corner, Section 36. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 25) Established the position for the corner midway and on the Section line between Section corner 1307.68' east and Quarter corner 1307.68' west.

(5-Sec. 36) Established the position for the corner midway and on a straight line between Quarter corner 1327.62' north and Center of Section 36 1327.62' south. The position for the corner falls in Butterfield Lake and was not monumented. Established a WITNESS CORNER on the N-S 1/4 line 167.00 feet south of the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Y.Birch N68°E 23.9' mrkd "1/16S BT"
8" Sugar S10°W 21.2' do
5" Sugar N72°W 17.5' do
4" Sugar N09°W 6.2' do
Set sq'd cedar post adjacent.
E= 7852044.476 N= 223664.805

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap
167.00' south of the corner position and on the
1/4 line. Set measuring nail with MDNR tag in:
5" Maple S60°E 12.25' mrkd "WC BT"
6" Hemlock S23°E 22.1' do
8" Hemlock S48°W 22.6' do
8" Maple S76°W 15.75' do
Set sq'd cedar post adjacent.
E= 7851634.499 N= 223222.015
Water's edge is 10 ft. north this date.

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83 (2011) Datum)
Coord. Ref.=NGS PID RL0607: N= 222113.185 m. E= 7850163.394 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/30/2014

For the Michigan Department of Natural Resources, Forest Resources Division

