

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 15 T 51N R 37W S _____ T _____ R _____ S _____ T _____ R _____	H6 (GCDB 440440)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

I, Stephan J. Szyszkoski, in a field survey on 08/19/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Center of Section 15. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners. The position for the corner falls at the edge of a creek and a monument at that position might wash out in times of flooding. Therefore, I left the position unmonumented and placed two WITNESS CORNERS: The first being 13.06' north of the corner position and on the N-S 1/4 line; the second being 10.71' west of the corner position and on the E-W 1/4 line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2"IDx28" I.pipe with 2" alum. MDNR cap 13.06' north of the corner and on the N-S 1/4 line.
Set measuring nail with MDNR tag in the side of:
12" B.Ash N52°E 33.0' mrkd "WC BT"
14" Cedar S75°E 40.2' do
10" Spruce N09°W 28.0' do
1" capped pipe W.C. West of H6 S46W 17.58'
Set sq'd cedar post adjacent.
E= 7848546.209 N= 227760.956 (C1/4 position)

Set 1"IDx28" I.pipe with 2" alum. MDNR cap 10.71' west of the corner and on the E-W 1/4 line.
Set measuring nail with MDNR tag in the side of:
4" Elm S81°W 34.4' mrkd "WC BT"
14" Y.Birch in clump N68°W 28.5' do
5" Cherry N48°W 5.0' do
1" capped pipe W.C. North of H6 N46E 17.58'
Set sq'd cedar post adjacent.

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Signed by Stephan J. Szyszkoski Date 08/26/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

