

DEC 16 1996

COMMISSION

JUDITH D. ROEHM  
Ontonagon County  
LC 4/ 78 JEM Fee: 9.00  
Page 1 of 1

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Ontonagon  
(County)

Located In:

Corner Code #

- |   |   |     |   |     |      |
|---|---|-----|---|-----|------|
| 1. Public Land Survey                   | T | 51N | R | 38W | B-13 |
|   | T |     | R |     |      |
|   | T |     | R |     |      |
|   | T |     | R |     |      |
| 2. Property Controlling<br>in Section   | S |     | T | R   |      |
|   | S |     | T | R   |      |
| 3. Miscellaneous<br>Property in Section | S |     | T | R   |      |
|   | S |     | T | R   |      |

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Joseph C. Domitrovich, in a field survey on June 5, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B-13) South 1/4 Corner, Section 31, T51N, R38W

1845 - Austin Burt set post

14" Sugar	N 38° E	13 Links
8" Sugar	N 12° W	18 Links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found no remaining evidence of GLO corner. Re-established east-west corner position by proportionate measurement between the closing corner Sections 3 & 4, T50N, R39W and the standard corner Sections 31 & 32, T51N, R38W. Re-established north-south position by placing corner on the township line between standard corners to east and west.

This position falls S 40° E 51' from a 1968 Copper Range location poster on a down Birch tree. "App. 1/4 COR" was noted on the poster.

PEER GROUP APPROVED

Earl W. Applkamp  
COUNTY REPRESENTATIVE 6-86-96

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to read: T.51N., R.38W.; 1/4 S. 31; 1996 P.S. 37273

Witnesses:

6" hard Maple	N 80° E	26.15'
6" Hard Maple	S 17° E	7.00'
12" Hard Maple	S 40° W	6.13'
10" Hard Maple	N 48° W	15.94'
Steel Sign Post	North	0.91'

**NOTE:** Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Signed by J. C. Domitrovich

Date 6/5/96

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN, 1983

