

MAR 02 2001

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Ontonagon County	Located in:	Corner Code #
1. Public Land Survey	T51N R38W	G - 7
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No.	Recorded Plat	
5. Private Claims		

JUDITH D. ROEHM 1P
Ontonagon County
Page 1 of 1 LC 5/352
JEM Date 12/08/2000 Time 11:39:34
RECORDING FEE: 9.00

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Joseph C. Domitrovich, in a field survey on November 8, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G - 7) Corner Common to Sections 15, 16, 21, & 22, T51N, R38W.

1846 - H & S.W. Higgins set a post with ties:

12" Lynn	S 80°W	42 links
12" B. Ash	N 40°E	30 links

1997 - Mead Paper Corner Records indicate that there is a 1 1/4" iron pipe with a 90° Elbow at this corner.

8" Soft Maple	N 36°E	12'	(Metal tag)
9" Basswood	S 10°W	6'	(Yellow tag)
15" Aspen	North	16'	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. At the corner position I found the iron pipe as called for by Mead records. Old blazes and location posters facing this corner indicate that this pipe has been used and accepted as the true corner for many years. Distances to other corners in the area differ considerably from record GLO but this is not inconsistent with work done elsewhere in this township by the original surveyors. I have accepted the iron pipe as the best representation of the true section corner.

Research on file with County Remonumentation Representative.

DEER GROUP APPROVAL
Earl W. Applekamp
COUNTY REMONUMENTATION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 11-29-00

I sawed off the iron pipe at ground level and drove a 3/4" x 48" aluminum rod inside of it and placed a 3" diameter aluminum cap on it stamped to read: COUNTY REMONUMENTATION; T51N, R38W; S. 15, S. 16, S. 21, S. 22; 2000; P.S. 37273. Ties:

7" Ash	N 17°E	5.73'	(Existing Blaze & Yellow Calumet & Hecla Location Poster)
Steel Sign Rail	South	0.58'	(to face)
6" Soft Maple	S 33°W	13.96'	(Existing Blaze & Copper Range Location Poster)
5" Hard Maple	S 69°W	14.86'	
N 1/4 Cor. Sec. 22	N 88°26'42"E	2711.98'	
W 1/4 Cor. Sec. 22	S 02°40'19"E	2644.80'	

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

Signed by J.C. Danah

Date 11/28/00

Surveyor's Michigan License No. 37273

