

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon Located In: Corner Code #
1. Public Land Survey T 52N R 37W F11
2. Property Controlling in Section S 33 T 52N R 37W 5
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 09/08/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F11) Quarter corner common to Sections 28 & 33. 1992 - Previously recorded by K.L.Sackett RLS: Found 1 1/2" ID pipe and Vulcan location poster. 7" Hemlock S42°W 12.5'; 8" Ironwood S42°E 9.6'; 12" Sugar N64°W 28.4'; 4" Ironwood N53°E 23.0'.

(5-Sec. 33) Center-North 1/16 corner, Section 33. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F11) Found the 1999 monument of record, in good condition, and at substantial record bearing and distance from three existing 1999 witnesses.

(5-Sec. 33) Established the position for the corner midway and on a straight line between Center of Section 33 1326.03' south and Quarter corner 1326.03' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F11) Found 1.5" ID I.pipe, 18" a.g. Set measuring nail with MDNR tag in the side of: 11" Hemlock S44°W 13.45' old blazes (1999 NBT) 14" Sugar N64°W 28.8' do do 5" Ironwood N53°E 22.65' do do 5" Sugar S40°E 18.0' mrkd "1/4S NBT" E= 7847024.026 N= 233446.579

(5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 16" Sugar N27°E 13.75' mrkd "1/16S BT" 5" Sugar S82°E 19.1' do 11" Sugar S13°E 23.9' do 17" Sugar S85°W 4.4' do Set sq'd cedar post adjacent. E= 7847019.126 N= 233042.471

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0503: N= 233736.672 m. E= 7856830.965 m.

Signed by [Signature] Date 09/23/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division