

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Presque Isle

(County)

Located In

Corner Code #

1. Public Land Survey	T	33N	R	4E	E-10		
	T		R				
2. Property Controlling in Section	S	29	T	33N	R	4E	15
	S		T		R		
3. Miscellaneous Property in Section	S		T		R		
	S		T		R		

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on January 29, 2002 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-10 G.L.O. - Alfred Millerd D.S. 1855

Set quarter section post

Wit: Yellow Pine 10 N53°E 18 links

White Pine 12 S60°W 9 links

15- This corner position was not established during the original government survey.

Page 687, Presque Isle County Land Corner Records June 1986 Carl R. Johnson L.S. #30083 set corner by single proportionate measure between section corners. Set DNR monument

Wit: 6" Jack Pine N48°E 25.5'

5" Red Maple S70°E 53.2'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-10 Found D.N.R. monument and cedar post

15- Established the Southeast corner of the Southwest quarter of the Southwest quarter of section 29 as per B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-10 D.N.R. monument and cedar post

Wit: 5" Jack Pine N78°W 48.13'

5" Jack Pine S15°W 33.75'

4" Red Pine S68°E 30.28'

\*8" Jack Pine N56°E 25.88'

Carsonite Post North 1'±

15- Set 5/8" X 32" rered with P.S. cap #33981

Wit: 4" Red Pine East 22.52'

3" Maple N72°W 41.55'

3" Maple N12°E 23.97'

5" White Pine S10°E 61.42'

Carsonite Post North 1'±

\* Old witnesses by others

Signed by:

Carl T. Kiiskila

Date:

8-26-02

Surveyor's Michigan License No.:

33981

