

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
PRESQUE ISLE
 (County)

Located In: _____ Corner Code # _____

- | | | | | | |
|------------------------------------|---|------------|---|-----------|------------|
| 1. Public Land Survey | T | <u>34N</u> | R | <u>4E</u> | <u>1-7</u> |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| 2. Property Controlling in Section | S | _____ | T | _____ | R |
| | S | _____ | T | _____ | R |
| 3. Miscellaneous Property in Sec. | S | _____ | T | _____ | R |
| | S | _____ | T | _____ | R |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, CARL T. KIISKILA, in a field survey on JANUARY 13, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
 [- 7]

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 [- 7]

FOUND AND ACCEPTED A 1/2" REBAR WITH D.PORTER RLS CAP AT A FENCE CORNER WITH SMOOTH WIRE GOING N & E. THIS CORNER HAS BEEN ACCEPTED BY LAND OWNERS AND OTHER SURVEYORS FOR SURVEYS IN THE AREA.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 [- 7]

FOUND 1/2" ROD - PORTER'S - SET 1" x 32" IRON PIPE W/ALUMN. DNR CAP. SET CARSONITE POST.
 14" W.PINE N78°E 23.68'
 12" MAPLE N62°W 35.32'
 18" OAK S18°W 16.89'
 16" MAPLE S29°E 27.19'

* OLD DWITS BY D.PORTER, RLS, NOT RECORDED.



Signed by Carl T. Kiiskila Date 2-27-97

Surveyor's Michigan License No. 33981