

1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

PRESQUE ISLE COUNTY
RECORDED

93 DEC 22 AM 10:01

Janet M. Lamb
REGISTER OF DEEDS

For corners in

PRESQUE ISLE
(County)

Located in:

Corner Code #

1. Public Land Survey T 34NR 2E C-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, DELMER E. PORTER a field survey on SEPT. 8, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law, established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	16		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-7 GLO NOTES

HEMLOCK 12" S 21° W 22 lks.

SUGAR 10" N 44° E 20½ lks.

WITNESSES

S 63° W 80.30' P. POLE

S 66° W 65.12' STOP SIGN

N 62° E 60.30' STOP SIGN

C-7

P.A. 74 FILING BY RONALD R. BISCHER

L.S. 22428 JUNE 7, 1988 PAGE 715

LAND CORNER RECORDS

FOUND 1½" PIPE IN MONUMENT BOX BY M.S.H.D.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-7

SEPT. 8, 1993

FOUND 1½" PIPE IN MONUMENT BOX

S 63° W 80.30' P. POLE

S 66° W 65.12' STOP SIGN

N 62° E 60.30' STOP SIGN

Ratified by Peer Group
in accordance with P.A. 345

Chairman *Delmer E. Porter*

Date December 18, 1993

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-7

1½" PIPE IN MONUMENT BOX

N 33° W 197.29' 12" MAPLE

S 62° E 185.06' 8" MAPLE

S 37° E 173.45' 8" MAPLE

S 59° W 165.81' 6" MAPLE

* NAILS AND TAGS #15410 USED ON WITNESSES

PORTER'S SURVEY, P.C.

Signed by

Delmer E. Porter

Date

Dec 20, 1993

Surveyor's Michigan License No.

15410

CORNER HISTORY RESEARCH SHEET

C-7

T34N,R2E ALLIS TOWNSHIP-NORTH PART,
PRESQUE ISLE COUNTY, MICHIGAN.

ACTIVITY	MONUMENT & ACCESSORIES	COMMENTS
----------	------------------------	----------

GLO Survey
July 17, 1855

Hemlock 12" S21°W 22 Links
Sugar 10" N44°E 20 1/2 Links

Act 132 Survey by
Delmer E. Porter #15410
Recorded Oct. 16, 1978
SUR#69-78 File#34R2094

Iron Rod in Mon. Box

Act 132 Survey by
Delmer E. Porter #15410
Survey May 12, 1985
Recorded Feb. 29, 1988
SUR#84-84 File#34R2162
Liber 279, Page 721

1" Iron Bar in Mon. Box
S42°E 93.75' 6" Elm
S46°W 51.63' 11" Maple
N69°W 112.42' 12" Elm

Act 74 filing by
Ronald R. Bischer
#22428, June 7, 1988
Page 715, Corner
Recordation

Found 1 1/2" Pipe in Mon. Box
By M.S.H.D.
Left 1 1/2" Pipe in Mon. Box ✓
S63°W 80.30' P. Pole
S66°W 65.12' Stop Sign
N62°E 60.30' Stop Sign

Act 132 Survey by
Norman J. Quaine #33984
March 27, 1993
SUR#155-92 File#34R2270
Not Recorded

1" Iron Bar in Mon. Box
S42°E 93.75' 6" Elm
S46°W 51.63' 11" Maple
N69°W 112.42' 12" Elm

Remonumentation
Sept. 8, 1993

FD. 1 1/2" Pipe in Mon. Box
S63°W 80.30' P. Pole
S66°W 65.12' Stop Sign
N62°E 60.30' Stop Sign
Left Same
N33°W 197.29' 12" Maple
S62°E 185.06' 8" Maple
S37°E 173.45' 8" Maple
S59°W 165.81' 6" Maple

SURVEY &
MONUMENTATION

JAN 22 2001

SECTION

B.A.E.
#3