

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Presque Isle
 (County)

Located In:

Corner Code ##

- | | | |
|-------------------------|---|-------------|
| 1. Public Land Survey | T <u>34NR 5E</u> | <u>B-9</u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| 2. Property Controlling | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| in Section | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| 3. Miscellaneous | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| Property in Sec. | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |

PRESQUE ISLE COUNTY
RECORDED

96 JUN -4 AM 11:26

John M. Lamb
 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
 5. Private Claims

I, Norman J. Quaine in a field survey on December 11, 19 95,
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
 current manual of survey instructions of the United States Department of the Interior, Bureau of Land
 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
 Court of Law; established, re-established, monumented, re-monumented, recovered, found as
 expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
 on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-9	Dec. 10, 1984
1856	LCRC
Subdivisions by	Delmer E. Porter LS#15410
Alfred Millerd	Set 1/2" Rod & Cap #15410
Deputy Surveyor	in trail C/L at Inter. of
Set Quarter Sec. Post	Sec. line & 1/4 Line Fences
Hemlock 10 N45E 10	N44° E 51.40' 4" Balsam
Cedar 8 S20W 16	S81° E 47.74' 10" Cedar
	S05° W 37.78' 8" Maple

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-9	
December 11, 1995	Fd. 1/2" Rod & Cap #15410
Norman J. Quaine	N44° E 51.49' 5" Balsam
P.S.#33984, Porter's	S81° E 47.80' 10" Cedar
Survey P.C.	S05° W 37.91' 10" Maple
1996 P.I. Co. State	
Remonumentation	

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-9
 Left 1/2" Rod & Cap #15410
 N44° E 51.49' 5" Balsam
 S81° E 47.80' 10" Cedar
 S05° W 37.91' 10" Maple
 S18° E 26.36' 4" Cedar

*witness tags & nails.

Ratified by Peer Group
 in accordance with P.A. 345

Chairman *Delmer E. Porter*Date 5/22/96

Porter's Survey P.C.

Signed by *Norman J. Quaine*Date MAY 22, 1996Surveyor's Michigan License No. 33984