

State of Michigan Remonumentation Program
For Presque Isle County

PRESQUE ISLE COUNTY
RECORDED

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

94 SEP -6 AM 10:11

For corner to
**SURVEY &
REMONUMENTATION**
(County)

Located In:

Corner Code #

1. Public Land Survey **APP 25 1995**

T 36N R 2E

A-MP

COMMISSION

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

Other #8

LIBER **311** PAGE **134**

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, **Norman J. Quaine** in a field survey on **June 30**, 19 **94**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-MP

GLO Notes

Resurvey 1856

Y. Pine 16" N73°E 20 Lks.

Y. Pine 12" N18°W 48 Lks.

10-4-76

Porter's Survey File

Records

L.C.R.C.

Delmer E. Porter

#15410

Found 2" Pipe while performing
Survey in Section 30

Left 2" Pipe

N03°W 35.81' 10" Norway

S52°E 72.99' 16" Spruce

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-MP

6-30-94

Presque Isle County

State Remonumentation

Norman J. Quaine

#33984, Porter's Survey, P.C.

Found 2" Pipe

4' East of Black Lake

S47°E 73.11' 19" Spruce

N01°E 35.87' 13" Norway Pine

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-MP

2" Pipe

S47°E 73.11' 19" Spruce

N01°E 35.87' 13" Norway Pine

S83°E 40.72' 20" Oak

N49°E 18.77' 9" Balsam

Ratified by Peer Group
in accordance with P.A. 345

Chairman *Delmer E. Porter*

Date *Aug 27, 1994*

Signed by

Norman J. Quaine

Date

Aug 17, 1994

Surveyor's Michigan License No.

33984