

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>36</u> N. S., R. <u>3</u> E.	H-11; H-12;
2. PROPERTY CONTROLLING IN SECTION	<u>34</u> T. <u>36</u> N. S., R. <u>3</u> E.	<u>8</u>
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. S., R. _____ E.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, KENNETH J. OSTLING, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on APRIL 11, 1983, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XX

C. CONTINUED

H-12
 SET 5/8" ROD W/RLS CAP & CEDAR POST
 6" CEDAR S29°E 37.3'
 8" R. OAK N13°W 19.3'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8 - SET CORNER BY STANDARD SURVEY PROCEDURE FOR THE SUBDIVISION OF SECTIONS.

H-11 - SET CORNER MIDPOINT ON LINE BETWEEN SECTION CORNERS. THE 1/2" IRON BAR WAS APPARENTLY SET IN ERROR DURING A PREVIOUS SURVEY, THE RECORD OF WHICH INDICATES THE INTENT TO SET ON LINE AT MIDPOINT.

H-12 - SET BY STANDARD SURVEY PROCEDURE, AT THE CALCULATED INTERSECTION OF THE TRUE 1/4 LINES.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>8</u>	<u>H-11</u>
SET 5/8" ROD W/RLS CAP & CED POST	SET 5/8" ROD W/RLS CAP (BURIED)
7" J. PINE S68°W 8.0'	12" R. OAK N27°W 36.7'
8" J. PINE N87°E 10.1'	8" R. PINE S16°E 45.5'
FENCE CORNER S62°E 32.5'	CEDAR POST SOUTH 15'
	1/2" Iron bar N88°09'W 49.93

SIGNED BY Kenneth J. Ostling

DATE 11/9/83

SURVEYOR'S MICHIGAN REGISTRATION NO. 10068

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____

DATE _____

APPROVED AND SIGNED BY _____

MICHIGAN REGISTERED LAND SURVEYOR

DATE _____

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

PRESQUE ISLE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
 REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET