

REMONUMENTATION SURVEY & REMONUMENTATION
APR 10 1995
COMMISSION

LIBER 2 PAGE 1
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

94 DEC 16 AM 9:40

LIBER NO. 2 PAGE NO. 1
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in
Sanilac
(County)

Located In:

Corner Code #

1. Public Land Survey T 10N R 13E B - 13
T R
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, John A Milletics, in a field survey on Sept 13, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B - 13 GLO Notes
Set 1/2 Mile Post Ash 20 N 71 W 27, Ash 9 N 65 E 33

Act 74 Form None
Act 132 Form Liber 3 Page 631, Liber 4 Page 387
Unrecorded survey Dated 6-20-91
Road Comm None
Drain Comm None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B - 13
S 1/4 Cor Section 31 T10N-R13E
Found 1/2" iron bar

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B - 13
S 1/4 Cor Section 31 T10N-R13E
Found 1/2" iron bar
S20°E 27.23 to a nail in a 8" Twin Ash
S45°W 45.82 to a nail in a 8" Twin Ash
North 24.78 to a nail in a Wooden Fence Post
S75°E 85.50 to a nail in a 12 Poplar
West 37.00 to a 1/2" Iron in road bed(N 1/4 Section 6)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Approved Peer Board Meeting
Dec. 16, 1994 gm

Signed by

John A Milletics

Date

Dec 7, 1994

Surveyor's Michigan License No.

25859

