REMONUMENTATION

94	AUG	12	Y17	7	31	
•						/ <

C	REMONUMENTATION corners in	LAND COR Filing Requ	NER RECORDATION CERT sirement of Act 74, Mich. P	A. 1970 LIBER NU / PAI	GE 110.459 FE
	Sanilac (County)	Located In:	Corner Code ##	A. 1970 LIBER NO. ZANTER L REGISTER OF SANILAC CO., M	JEEDS ICHIGAN
1.	Public Land Survey	T 10N R 16E T R R			
2.	Property Controlling in Section	T R S T R S T R			
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stam	p & File Number
-1	Lot No, F	Recorded Plat		A B C D E F	GHIJKLW
با (10	John A Milletics	, in a field survey on <u>Ju</u> quirements of P.A. 74, Michigan P	.1y 16 , 19 94 A. of 1970, the corner points mentiand rules therefore as required in	2 6 5 4 3 4 7 8 9 0 ned 6 1 7 1 8	3 2 1 - 12 - 13 - 13 - 13
Jur Mai abc Coi exp	rent manual of survey instr nagement or by a decree of ove were in conformance wi urt of Law; established, pressed below:	uctions of the United States Dep a Court of Law and/or that the co th the rules of the Michigan Boar re-established, monumented, r	partment of the Interior, Bureau of rner points mentioned in lines 3, 4 of Land Surveyors or by a Decree-monumented, recovered, four and range, may be recorded	Land 7	27 26 25
	on this certificate.			12 31 32 33	35-36-
A.	Description of original	monument and accessories	and/or subsequent restoration	13 <u> </u>	
	Monu Box as reco	orded in Liber 4 on F nu Box in centerline	op over former locati age 74 of the Sanilac of U.S. 25 and Harrin	Co. Records	
	per Flat records	d Liber 3, Page 91		Approved Pec Aug. 9, 1994	er Board Meeting
				· ·	SM
3.	Description of corner of M - 8 E 1/4 Cor Section Found P.K. Nail		d applied in restoring or reest	ablishing corner:	
	M - 9		SURVE	V &	
	SE Cor Section 2 Found Monu Box	4 TION-RIDE	REMONUME		
	•		SEP 071	994	
			COWME	Richard &	
S.	M - 8 E 1/4 Cor Section Monu Box S85°W 49.50 to a S35°E 84.00 to a N35°E 91.60 to a	on 24 T10N-R16E a nail N side of a Te a nail SW side of a F	M - 9 SE Cor Sec Monu Box Ale Pole S45°W 56.4 Power Pole West 1.50 N45°W 67.8	cating the position of the correction 24 T10N-R16E to the NE Cor of Mictor to the centerline of to a nail N side of to a nail N side of	higan Bell Box U.S. 25 a Tele Pole
3ig	ned by John	4 Millities	Date	July 24 94	
Sur	veyor's Michigan Licens	e No. 25859		FORM APPROVED BY MICHIGAN STATE BOARD O	F LAND SURVEYORS, SAN 28, 1971
	· -			where we make the control of	REVISED MAY 14, 1975 REVISED JAN., 1983