

JAN 22 2001

RECEIVED FOR RECORD

LIBER 3 PAGE 74

00 DEC -1 AM 9:33

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

2000 REMONUMENTATION PROGRAM

LIBER NO. 3 PAGE NO. 74  
MICHELE VANNORMAN  
REGISTER OF DEEDS  
SANILAC CO., MICHIGAN

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey

T11N R16E

F - 7

T R

T R

T R

S T R

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

2000

John A Milletics, in a field survey on May 1, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5				4		3		2		1	
3													
4	7	6				9		10		11		12	
5													
6	18	17				16		15		14		13	
7													
8	19	20				21		22		23		24	
9													
10	30	29				28		27		26		25	
11													
12	31	32				33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

F - 7

GLO Notes

Hemlock 26" S49°E 16 Links

Beech 22" N05°W 20 Links

Act 132 - Liber 3 Page 534 Chope May 1976 - Liber 3 Page 133 Chope Aug 1974

Unrecorded surveys - Milletics Nov 1996 - Milletics June 1997

L.C.R.C. Forms - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F - 7

S 1/4 Corner Section 16 T11N-R16E

Found 3/4" Iron Pipe in gravel road bed

West 2658.64 feet to the SW Corner Section 16

East 2659.60 feet to the SE Corner Section 16

Accepted as best evidence

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F - 7

S 1/4 Corner Section 16 T11N-R16E

3/4" Iron Pipe in gravel road bed

North 35.00 feet to the center of the E-W gravel centerline

N80°E 15.45 feet to a stop sign

N70°W 33.15 feet to a stop sign

West 59.30 feet to the south end of a 12" CMP

N50°E 41.60 feet to a road sign

West 2658.64 feet to the SW Corner Section 16

East 2659.60 feet to the SE Corner Section 16

APPROVED PEER BOARD  
MEETING NOV 25 2000

Signed by

*John A Milletics*

Date Nov 15, 2000

Surveyor's Michigan License No. 25859