

JAN 22 2001

SECTION

LIBER 3 PAGE 73

2000 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

00 DEC -1 AM 9:33

LIBER NO. 3 PAGE NO. 73
MICHELE VANHORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

Sanilac Located in: Corner Code #
(County)

1. Public Land Survey T 11NR16E G - 7
T 1 R
T 1 R
T 1 R
T 1 R

2. Property Controlling S 1 T 1 R
in Section S 1 T 1 R
3. Miscellaneous S 1 T 1 R
Property in Sec. S 1 T 1 R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

2000

John A Millettics, in a field survey on May 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, uncovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

G - 7

GLO Notes

Beech 10" N82°E 30 1/2 Links

Beech 8" S45°W 1 Link

Act 132 - Liber 3 Page 133 Choze Aug 1974 - Liber 3 Page 534 Choze May 1976

Unrecorded surveys - Millettics Nov 1996 - Millettics June 1997

L.C.R.C Forms - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G - 7

SE Corner Section 16 T11N-R16E

Found 1/2" iron bar in gravel road bed

West 2659.60 feet to the S 1/4 Corner Section 16

East 2654.10 feet to the S 1/4 Corner Section 15

Accepted as best evidence

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G - 7

SE Corner Section 16 T11N-R16E

1/2" Iron Bar in gravel road bed

North 33.00 feet to a 1/2" Iron bar with cap

N30°E 29.80 feet to a nail in a 12" Cedar

N50°E 37.10 feet to a nail in a 12" Cedar

N70°E 61.20 feet to a nail in a 12" Cedar

S50°W 31.55 feet to the NE Corner of a Mail Box Post

West 2659.60 feet to the S 1/4 Corner Section 16

East 2654.10 feet to the S 1/4 Corner Section 15

APPROVED PEER BOARD
MEETING NOV 25 2000

igned by John A Millettics

Date Nov 15, 2000

urveyor's Michigan License No. 25859