JAN 2 2 2001

3 PAGE 50 UBER

RECEIVED FOR RECORD

00 NOV 29 AM 11: 11

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ER NO. 3 PAGE NO. 9
MICHELE VANNORMAN
REGISTER OF DEEDS
SANILAC CO. MICHIGAN LIBER HO. 2000 REMONUMENTATION PROGRAM Corner Code #

Sanilac Located in: (County) 1. Public Land Survey T11NR 16E 1. Property Controlling Ţ in Section i. Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

, Recorded Plat . Private Claims

2000

John A Milletics, in a field survey on May 1 19X do hereby state that under equirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in onformance with regulations and rules therefore as required in the current manual of survey instructions of the nited States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or at the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan pard of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, covered, found as expressed below:

OTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	<u>A</u>	В	C	D	Е	F	G	H	I	J	ĸ	Ł	ŗ
				1		ĺ				T	T	T	
2	1	6-	1	5 I	十	4-	╅	- 3 -	1	2-	+	~ <u>1</u> -	_
3	-	+	+	┼-	╫	╁		+-	╁	-		-	-
4	\vdash	·	┼-	ė-	+-	_وٰ .	-	-10	╄	11-	_	-12	
5	L	L	1_	1_		1.	┸		_				
6				 17—		Ţ	1					Ţ	
	<u> </u>	18— [T	1		16– 	1	-15 I	\top	14 	+	-13- l	-
7	<u> </u>		1-	\vdash	\dagger	十	+	- -	+	+-	+	+	\dashv
8	1	9—	+-:	20	+	21	+	-22_	-	23_	\bot	-24	_
9	<u> </u>	<u> </u>	<u> </u>	L	1_		\perp				┸		
10		<u></u>	L.	 29		 28]	١.			1	
			Π.	ا	Т	- 	T	-2 <i>i</i>	Τ΄	26— 	T	25 	٦
11	-			T	1	1	1	+	\vdash	1-	+	+	7
12	3	1—	-3	2—	 	33_	╁	34	⊢ :	5		36-	-
13		<u> </u>		<u>L_</u>	<u> </u>		L		<u>L</u>	L	L	1	╛

Description of original monument and accessories and/or subsequent restoration:

I - 1

GLO Notes

Hemlock 20" so8°W 19 Links

White Ash 9" 22°E 4½ Links

Act 132 - Liber 4 Page 202 Huron Surveying

Liber 5 Page 165 Milletics

L.C.R.C. Forms - None

State Highway Right of Way Book - Page 74

Unrecorded surveys - Milletics June 1992-Milletics Nov 1994- Miletics July 1995

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

T - 1

NE Corner Section 3 T11N-R16E

Found on evidence of corner on site - Removed by State Highway Department

during construction

2669.30 feet to the N 1/4 Corner Section 3

East 2642.28 feet to the N 1/4 Corner Section 2

Accepted as best evidence

APPROVED PEER BOARD MEETING Nov 25, 2000

Inha A. Millighto

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

NE Corner Section 3 T11N-R16E

1/2" Iron Bar with cap in concrete

West 46.85 feet to the SW Corner of Section 35

NO5°E 36.18 feet to a nail in a Power Pole

N40°W 40.17 feet to a nail in a 20" Cedar

 $S40^{\circ}E$ 40.45 feet to the top center of a Fire Hydrant

S40°W 67.75 feet to a nail in a Anchor Pole

West 2669.30 feet to the N 1/4 Corner Section 3

East 2642.28 feet to the N 1/4 Corner Section 2

rveyor's Michigan License No.___ 25859

Nov 15, 2000 Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971