

JAN 22 2001

LIBER 3 PAGE 71

RECEIVED FOR RECORD

SECTION

2000 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

00 DEC -1 AM 9:33

LIBER NO. 3 PAGE NO. 71
MICHELE VANHORMAN
REGISTER OF DEEDS
SAHILAC CO. MICHIGAN

For corners in

Sanilac
(County)

Located in:

Corner Code #

1. Public Land Survey

T11N R16E		I - 7
T	R	
T	R	
T	R	
T	R	
T	R	
T	R	
T	R	

2. Property Controlling
In Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, John A Millettics, in a field survey on May 1, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I - 7

SE Corner Section 15 T11N-R16E

GLO Notes

Hemlock 20" S71°W 31 Links

Cedar 12" N78½°E 24 Links

Act 132 - None

UNrecorded surveys - Millettics Oct 1982- Millettics Jan 1998 - May 1998

L.C.R.C. Forms - None

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I - 7

SE Corner Section 15 T11N-R16E

Found 3/4" Iron Bar in gravel road bed

West 2654.10 feet to the S 1/4 Corner Section 15

East 2703.88 feet to the S 1/4 Corner Section 14

Accepted as best evidence

2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I - 7

SE Corner Section 15 T11N-R16E

3/4" Iron Bar in Gravel Road Bed

S30°E 65.50 feet to a nail in a Power Pole

N45°W 38.65 feet to a nail in a 18" Ash Tree

N60°W 54.65 feet to a nail in a 24" Ash tree

N20°W 33.35 feet to a stop sign

S60°E 47.50 feet to a cable sign post

West 2654.10 feet to the S 1/4 Corner Section 15

East 2703.88 feet to the S 1/4 Corner Section 14

APPROVED PEER BOARD
MEETING NOV 25 2000

igned by John A Millettics

urveyor's Michigan License No. 25859

Date Nov 15, 2000