

JAN 22 2001

LIBER 3 PAGE 68

RECEIVED FOR RECORD

SECTION

2000 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

00 DEC -1 AM 9:33

For corners in

Sanilac
(County)

Located in:

Corner Code #

LIBER No. 3 PAGE No. 68
NICHELE VANHORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

1. Public Land Survey

T 11N R 16E J - 1

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

S

T R

S

T R

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

I, John A Millett in a field survey on May 1, 2000
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in
conformance with regulations and rules therefore as required in the current manual of survey instructions of the
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan
Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,
recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	P
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

J - 1

N 1/4 Corner Section 2

GLO Notes

None

Act 132 - None

Unrecorded survey - none

Village of Port Sanilac Assessor's Plat No 1 Recorded on Slide 280
show corner .

L.C.R.C. Forms - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J - 1

N 1/4 Corner Section 2 T11N-R16E

Found no evidence of corner on site - State Highway Department removed
during construction

West 2642.28 feet as recorded on plat to the NW Corner Section 2

Accepted as best evidence

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J - 1

N 1/4 Corner Section 2 T11N-R16E

1/2" Iron Bar with cap in pavement

West 49.13 feet to the S 1/4 Corner Section 35

N10°W 34.70 feet to the SW Corner of a building

S50°E 58.35 feet to the NE Corner of a building

S20°W 34.60 feet to the NW Corner of a building

S25°W 27.10 feet to the face of a Light Pole

West 2642.28 feet to the NW Corner Section 2

APPROVED PEER BOARD
MEETING NOV 25 2000

Signed by

Surveyor's Michigan License No. 25859

Date Nov 15, 2000

