

✓

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES  
  
LAND CORNER RECORD

Schoolcraft COUNTY


T 41-42N R 14W

DESCRIPTION OF CORNER  $\frac{1}{4}$  Corner bet. Secs. 1-36

CORNER MONUMENT  $\frac{1}{2}$ " x 16" Iron Pipe (buried)

DATE MONUMENT PLACED AND WITNESSED 8/10/67

WITNESSES TO CORNER..... No witnesses



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced in intersection of roads; East, West, South and in line with fence to North.

Corner lies 20' South of the corner fence post.

This position supported by testimony of Mr. Dixner, a local resident who remembers an iron being here and pulled by grader blade in the past.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 3/9/72

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing 2

R 4047  
Rev. 10/68