

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42-43 N.R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 5-32

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 5-23-61

WITNESSES TO CORNER..... 6" Hard Maple (1/4 S NBT) N72°W 32 1/2 Links



CIRCLE CORNER REGISTERED

9" Hard Maple (1/4 S NBT) S15°E 38 links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two Section Corners. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 28, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler