

SCHOOLCRAFT COUNTY PEER GROUP APPROVED

DATE 10/10/00 DOB

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &
REMONUMENTATION

FEB 08 2001

SECTION

For corners in

Schoolcraft
(County)

Located In:

Corner Code #

SIGRID HEDBERG

SCHOOLCRAFT CO. REGISTER

1P

Page 1 of 1

JLV Date 12/19/2000

LC 4/376

Time 11:53:21

1. Public Land Survey

T 42N R 14W

J1 ✓

T 43N R 14W

J13

T R

T R

T R

T R

T R

T R

2. Property Controlling
in Section

S

S

S

S

3. Miscellaneous
Property in Sec.

S

S

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Thomas P. O'Brien, in a field survey on 10/9/00, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Oct. 20, 1850 Algernon Merryweather, DS set gr. section post Spruce 6 N42E 9
do 5 N32W 11

Sept. 15, 1961 Billy D. Buckler, RLS "This corner was placed midway and on line between section corners. No original evidence."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Oct. 9, 2000 Thomas P. O'Brien, PS found Mich. Dept. of Cons. cap on pipe as set by Buckler and verified by witnesses and distances to corners E and W. Accepted corner as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Michigan Department of Conservation cap on pipe.

Witnesses:

10" Cedar S50°W 10 links - exsisting Buckler BT

14" Cedar N18°E 14½ links- exsisting Buckler BT

8" Cedar N29°W 12.05'

6" Cedar S85°E 23.95'

Carsonite Post North 1.0'



Signed by Thomas P. O'Brien

Surveyor's Michigan License No. 21274

Date Dec. 12, 2000

LIBER 4 PAGE: 374

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1977
REVISED MAY 14, 1977
REVISED JAN., 1988
REVISED OCT., 1989