

SCHOOLCRAFT COUNTY PEER GROUP APPROVED

DATE 10/10/00 TDB

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &
REMONUMENTATION

FEB 08 2001

SECTION

For corners in

Schoolcraft

(County)

Located in:

Corner Code #

1. Public Land Survey

T 42N R 14W

L11

SIGRID HEDBERG

1P

SCHOOLCRAFT CO. REGISTER

Page 1 of 1

LC 4/398

JLO Date 12/19/2000

Time 11:53:35

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Thomas P. O'Brien, in a field survey on 10/31/00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

March 31, 1851 Algernon Merryweather, DS set 1/4 post Cedar 4 in Corner tree
Cedar 12 in N65E 2 links

Sept. 3, 1902 Eugene Ford, County Surveyor" set post under cross way new witness stump
cedar 8 in S70W 52 l. Cedar stump 12 in, S51E 28 l.

Dec. 30, 1989 Gary E. Koepke, RLS "re-established N $\frac{1}{4}$ Cor. Sec. 36 on line and midway between
NE. Cor. Sec. 36 and NW. Cor. Sec. 36.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Oct. 31, 2000 Thomas P. O'Brien, PS found 3/4" x 36" pipe with 26458 cap midway and on
line between K11 and M11. Reset with Schoolcraft County monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Schoolcraft County monument stamped to identify.

Witnesses:


12" Cedar S30°E 61.15'

4" Spruce S23°W 45.72'

Power Pole N80°E 133.27'

Power Pole N76°W 167.30'

Carsonite Post N5°E 25.0'



Thomas P. O'Brien

Signed by Thomas P. O'Brien

Surveyor's Michigan License No. 21274

Date Dec. 11, 2000

LIBER 4

PAGE 398