ELITY A EMONUMENT

SCHOOLCRAFT COUNTY

OCT 2 6 1995

COMMIS

11

12

EER GROUP APPROV	ED
DATE (hand 10 1995	LAND CORNER RECORDATION CERTIFICATE
DATE Mayor 10, 1773	LAND CORNER RECORDATION CERTIFICATE —Filing Requirement of Act 74, Mich. P.A. 1970

Schoolcraft (County)		Located	l in:	Corner Code ##	Received & Filed this 10 day of		
Public Land Survey		T 42N T T T	Sigrid I. Hedberg Schoolcraft Co. Reg. of Deeds				
2. Property Controlling	S		R		001100101111 00. 110g. 01 00000		
in Section	s	T	R				
3. Miscellaneous	s	T	R		Register of Deeds Stamp & File Number		
Property in Sec.	s	T	R				
4. Lot No ,	Recorde	d Plat	·		A R C D E E G H 1 J K I		
5. Private Claims							
					2 6 5 4 3 2 4 1		
					3* + + + + + + + + + + + + + + + + + + +		
Thomas P. O'Br	ion		Nov	7.30 ₁₉ 93	3 4 - 7 - 8 - 4 - 9 - 10 - 11 - 12 -		
THOMAS T. O DI	ታምክለ a fi	eld survey	on Live	19 7 -	' 5 <u> </u>		

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration:

A-3(N.W.Corner SEc.7)

expressed below:


Aug.3, 1845 John Burt Das.setmcorner post. Hemlock 8 N65W 31 do 6 S15W 46

Sept.27/50 Algernon Merryweather, D.S. Corner 6&7 West Boundary Hemlock 20 in. S59E 51 links Spruce 10" N41E 33 ".

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- A-3 June 8, 1965 Frank J. Bray, RLS set corner from rotted stumps of two probable BT's. Hemlock 6" S15W, 46 lks. and Hemlock 20" S59E 51 lks. Position checks good with distance South to swamp edge and stream. Old squared post in vicinity. Cedar register tree with names and dates back to 1940 near by. Distance South to Section Corner 80.76 chs., which is 76 lks. long but there seems to be a overrun throughout this township.

Nov.30, 1993 - Thomas P. O'Brien, PS recovered D.N.R.monument set by F.Bray. Bray witness 14" Y. Pine N54E 46 1/2 lks. cut.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1" pipe w/4" aluminum cap stamped to identify.
 16" White Pine N27W 13 lks.(8.58') Bray witness.
 6" Cedar S28W 24 1/2 lks.(16.17') Bray witness.
 6" Cedar S54E 48.85'(NBT)



Signed by	Thomas P.O'Brien,	PS	Date _	March 1	10, 1995	
Surveyor's Michiga	n License No. 21274					 160 48 467