

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
SCHOOLCRAFT
 (County)

Located In:

Corner Code #

- | | | |
|------------------------------------|-------------|------|
| 1. Public Land Survey | T 42N R 17W | M-13 |
| | T 42N R 17W | L-13 |
| | T 42N R 17W | K-13 |
| | T 42N R 17W | J-13 |
| 2. Property Controlling in Section | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

I, Gerald L. Wiggins, in a field survey on 10-9 & 10-11 & 11-29, 89, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

- M-13 S.E. Section Corner of Section 36. OBT'S: Beech 8", S76°W, 33 lks. & Beech 14", N47°W, 37 lks.
 L-13 South 1/4 Corner of Section 36. OBT'S: 12" Sugar, N17°E, 29 lks. & 3" Beech, N48°W, 15 lks.
 J-13 South 1/4 Corner of Section 35. OBT'S: 4" Hemlock, N37°E, 20 lks. & Sugar 20, N43°W, 24 lks.
 K-13 S.E. Section Corner of Section 35. OBT'S: Sugar 18, N50°E, 31 lks. & Beech 12, N33°W, 22 lks.


B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- M-13 Witnessed recorded monument as set by M.P. Davis L.S. #16926.
 L-13 Cor. set projecting a line from the S.E. Cor. of Sec. 36 across a conc. monument found at the East 1/16 Cor. on the south line of Sec. 36 and double the distance between them.
 J-13 Cor. set midpoint on line between the S.W. Corner and S.E. Corner of Section 35.
 K-13 Cor. set by single proportionate measure between the S.W. Cor of Sec. 35 and the South 1/4 Corner of Sec. 36.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | |
|---------------------------|-------------------------|----------------------------|
| M-13 Sq. Conc. Plat Mont. | L-13 DNR Monument | J-13 DNR Monument |
| 10" Maple, N71°W, 9.1' | 22" Maple, S07°W, 4.5' | 22" Y. Birch, N48°E, 22.0' |
| 10" Maple, S85°W, 20.9' | 24" Maple, N35°E, 26.6' | 16" Hemlock, N11°E, 39.7' |
| P. Pole, N40°E, 62.9' | 4" Balsam, N85°E, 14.2' | 16" Hemlock, N76°E, 17.4' |
| 6" Maple, S45°E, 69.5' | 8" Maple, S55°W, 23.0' | 6" Beech, S83°E, 3.1' |
| (Tag in tree) | | |
- K-13 DNR Monument. 10" R. Pine, N48°W, 39.15' & 8" R. Pine, N21°E, 27.3' & 8" R. Pine, N89°E, 81.2' & 10" R. Pine, S49°E, 100.05'.

Signed by Gerald L. Wiggins Date 3-19-90
 Surveyor's Michigan License No. 23521



FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, 1971
 AND REVISOR, 1979
 JAN. 1983