

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Schoolcraft

(County)

Located in:

Corner Code #

1. Public Land Survey

T R  
T R  
T R  
T R

2. Property Controlling  
in Section

S 27 T 42W R 17N 12  
S 27 T 42W R 17N 10

3. Miscellaneous  
Property in Sec.

S T R  
S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

10 Jun 02 2003

12 May 29 2003

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 20\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 27) South 1/16 corner, Section 27. Not established in the original survey.

(10-Sec. 27) South 1/16 corner between Sections 27 & 28. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 27) Established the corner midway and on a straight line between Center of Section and Quarter corner 1312.57' north and south.

(10-Sec. 27) Established the corner midway and on a straight line between Quarter and Section corners 1309.14' north and south. The corner falls on the west edge of a trail.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx36" I. pipe with 4" alum.  
MDNR cap. Blazed, scribed, and set  
measuring nails in:

12" Maple N66E 9.75' "S1/16 8T"  
10" Maple N28W 22.15' do  
8" Maple N31E 13.4' do  
14" Maple S35E 33.8' do

An old E-W fence is 1 ft. south.

Bearings are magnetic. Distances are to  
nail with tag.

(10) Set 1"IDx36" I. pipe with 4" alum.  
MDNR cap set flush with the ground.  
Blazed, scribed, and set measuring nails

in:  
6" R.Pine N42W 36.0' "S1/16 8T"  
6" W.Birch S50E 31.45' do  
6" R.Pine N72E 26.7' do  
4" W.Pine N15E 41.05' do

Set Cedar post adjacent. Bearings are  
magnetic. Distances are to nail with  
tag.

Signed by Stephan J. Szyszkoski

Surveyor's Michigan License No. 33986

Date

6/19/03



For the Michigan Department of Natural Resources - Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995