

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Schoolcraft

(County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 13W C13
 T R
 T R
 T R
 T R
 S T R
 S T R
 S T R
 S T R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

Jan 29 2002

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													


A. Description of original monument and accessories and/or subsequent restoration:
 (C13) Corner common to Sections 31-32 T44N-R13W and 5-6 T43N-R13W. Previously recorded in 1975 by D.B.Babbitt, RLS. 2" pipe with 2" brass cap set by Carl Christianson. 8" Cedar N53E 37.5', 13" Cedar N40W 34.6'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C13) Found the monument described in the 1975 record, in good condition, at record bearing and distance from the 1975 witnesses recovered as follows: N53E 37.5' Cedar stump, 1.5' high with markings visible, 18" Cedar N42W 34.6' with markings visible. Left the monument in place and made new witnesses as described below. The corner lies westerly of a curve in the road from East to NW.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C13) Found 2" iron pipe with 2" brass cap stamped 31-32-5-6. Blazed, scribed, and set measuring nails in:
 18" Cedar N42W 34.7' "S31"
 12" Cedar S02W 13.8' "S6 NBT"
 16" Cedar S89E 61.25' "S5 NBT"
 24" Cedar N62E 34.2' "S32 NBT"
 Bearings are magnetic. Distances to nail with tag.



Signed by

Stephan J. Szyszkoski

Date

4/16/02

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Office of Property Management

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1975
 REVISED JAN., 1983
 REVISED OCT., 1985