

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
SCHOOLCRAFT  
 (County)

Located in:

Corner Code ##

1. Public Land Survey	T	44N	R	16W	H11
	T		R		
	T		R		
	T		R		
2. Property Controlling	S	27	T	44N	R 16W
in Section	S	27	T	44N	R 16W
3. Miscellaneous	S		T		R
Property in Sec.	S		T		R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, Stephan J. Szyzskowski, in a field survey on June 30, 1992, 19\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

**A. Description of original monument and accessories and/or subsequent restoration:**

(H11) Quarter corner common to Sections 27 and 34, T44N-R16W. Corner established by U.S. Deputy Surveyor William Ives. Original bearing trees: White Pine 18 N37E 38, White Pine 20 S43W 30. Original line notes show: 1) East 7.54 ch. Stream 70 links Course S and from NW. 2) East 2.54 ch. Leave bottomland course SE. 3) West 20.46 ch. Enter swamp course NW and SE. 4) West 24.66 ch. Stream 2 links course NE. 5) West 40.04 ch. Section corner. (line calls were noted on the random run east and transcribed to the corrected line, run west.)  
 (10) South 1/16 corner between Sections 27 and 28, T44N-R16W. Corner not established in original survey. Found no subsequent record.  
 (15) West 1/16 corner between Sections 27 and 34, T44N-R16W. Corner not established in original survey. Found no subsequent record.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

(H11) Original post not recovered. Restored corner from the ground level remains of two white pine stumps, possibly the original bearing trees, both found at record bearing and distance. Stumps were in advanced stages of decay and no markings were found. Corner location corroborated with the record line calls referenced above as follows: 1) checks. This call is evidently to the west edge of the river, not the east edge as implied by the notes of the corrected line. It appears to have been derived from the random notes. 2) checks. 3) checks. This call is not well defined. 4) checks. 5) checks to a corner monumented from line calls.  
 (10) Established corner midway and on a straight line between Quarter corner 1324.33' North and Section corner 1324.33' south. Found no monumentation or evidence at this position.  
 (15) Established corner midway and on a straight line between Section corner 1319.02' West and Quarter corner 1319.02' East. Found no monumentation or evidence of use at this position.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

(H11) Placed a 1"x32" painted iron pipe capped with a 4" dia. cast aluminum MDNR tablet. Blazed, scribed, and placed measuring nails in the following new bearing trees: 15" W. Pine N37E 29.80' (1/45 NBT) 7" Jack Pine S80E 17.35' (1/45 NRT) 12" Red Pine S23E 25.0' (1/45 NBT) 7" Jack Pine S73W 6.51' (1/45 NBT) Placed a squared R. Pine post 1 foot West of the corner.	(10) Placed a 1"x32" painted iron pipe capped with a 4" dia. cast aluminum MDNR tablet. Blazed, scribed, and placed measuring nails in the following bearing trees: 18" W. Pine S25E 25.9' (1/16 BT) 6" Maple S34W 35.2' (1/16 BT) 6" Maple S67W 13.08' (1/16 BT) 7" Poplar N16E 55.53' (1/16 BT)	(15) Placed a 1"x32" painted iron pipe capped with a 4" dia. cast aluminum MDNR tablet. Blazed, scribed, and placed measuring nails in the following bearing trees: 14" W. Pine N49E 83.1' (1/16 BT) 5" Spruce S76E 63.46' (1/16 BT) 14" Maple N86W 84.0' (1/16 BT) 8" Maple N65W 70.9' (1/16 BT) Placed a 7" squared cedar post West 1'.
---	---	--

Signed by Stephan J. Szyzskowski

Surveyor's Michigan License No. 33986



7-20-92