

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47N N.R. 13W


Schoolcraft COUNTY

DESCRIPTION OF CORNER South 1/16 Corner bet. Secs. 13-18

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-7-70

WITNESSES TO CORNER..... 6" Jack Pine (1/16 BT) N33°W 19.6'



5" Jack Pine (1/16 BT) N20°E 18.2'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line between  $\frac{1}{4}$  Corner to north and Sec. Corner to south.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 10-19-70  
REGISTERED LAND SURVEYOR