

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 47 N.R. 15 W


Schoolcraft COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 23-24-25-26

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/8/64 with Miller

WITNESSES TO CORNER..... 16" Y. Pine (S24 NBT), N 65° E, 50 Lks.



12" W. Pine (S25 NBT), S 04° E, 46 1/2 Lks.

8" W. Pine (S23 NBT), N 05° W, 34 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from Yellow Pine stub, badly burned but notch and faces visible. (10" Y. Pine, S78° E, 25 Lks.) Down W. Pine to NW proper bearing and distance. (28" W. Pine, N22° W, 55 Lks.)

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 10/13/1964
REGISTERED LAND SURVEYOR