

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD ✓

T. ~~46-47~~ NR 16. W.

Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 6 and 31

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" Hard Maple (1/4" NBT) N 43° E 34 1/2 Links

12" Hard Maple (1/4" NBT) S 50° E 32 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced at old wood post set by unknown surveyor. Found
blazes at corner but no bearing trees.

Corner was placed and witnessed August 4, 1960.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 8/12/60